

3027 Dupont Avenue North



Rear - Needs all new windows/roof



Parking surface needs replacement



No overhang - water intrusion/cracking



Stucco failure and moisture intrusion



Settlement and stucco failure



Concrete need replacement



Mechanicals require replacement



Moisture present in basement



Water damage throughout



Kitchen requires replacement



Water damage from failing roof



Unsafe floors from water damage