

SRF Consulting Group, Inc.

Figure 5.10 – Improvements to Franklin Ave. Beneath Hiawatha Bridge