



TECHNICAL POLICY

13 – 81 “Plug” Type Tamper Switches

Original Issue: July 1986
Revised: April 2006

“**Plug**” or “**Lace**” type valve supervisory switches are not acceptable unless written approval is given by MFD Fire Prevention Bureau.