



TECHNICAL POLICY

13 – 08 Sprinkler Protection of Elevator Shafts and Equipment Rooms

Original Issue: August 1998

Revised: April 2006

Sprinklers are required only at the top of shafts that contain exposed combustible construction.