



## TECHNICAL POLICY

### 13 – 63      Updating Existing Hangers

Original Issue: June 2002

**Revised: April 2006**

When work is done on an existing sprinkler system that has pendent sprinklers on drops below a ceiling and the system pressure exceeds 100 psi, the existing hangers at the end of branch lines and on armovers shall be upgraded to prevent upward movement of the pipe as required by NFPA 13.

This policy applies to all rooms in which sprinkler work is being done.