



- 1 PROVIDE PROTECTIVE BUSHINGS ON ALL CONDUITS
- 2 ELECTRICAL CONDUITS AS SPECIFIED
- 3 KEEP SERVICE FEED TO LEFT OF BARRIER

NOTE:
 CABINET ANCHORS ARE HILTI KWIK BOLT II WEDGE ANCHOR OR EQUAL,
 4 PER CABINET, 1/2" x 4 1/2" STAINLESS STEEL (#304) FULL THREADED.

NO SCALE

	MINNEAPOLIS DEPARTMENT OF PUBLIC WORKS		FOUNDATION - SIGNAL CONTROLLER CABINET TYPE "P" AND SIGNAL SERVICE CABINET	STANDARD PLATE NO. TRAF-1069
	DRAWN: LPK	DATE: 12/2/10		
	APPROVED: DRP	DATE: 1/1/11		