

### Taariikhda Mashruuca

Iyada oo la dhisay 1941, buundada ka kooban todobada tiir ee dhererka ah ee dulmarta wadada tareenka ee BNSF, oo dhulka ka kacsan 142 dhudhun balaceeduna yahay 51 dhudhun, waa mid ay xaaladeedu ka sii dareyso. Iyada oo ay ugu wacan tahay dhaawac lagu arkay dhismaha buundada, waxaa si ku meel ah loo joojiyey in gaadiidku maro.

Inkasta oo daycatir lagu sameeyey oo si ku meel gaar ah loo furay buundada, xalka ku meel gaarka ah wuxuu iftiiminayaa baahida loo qabo in gebi ahaanba la bedelo si loo hubiyo hawsha ay qabaneyso iyo amaanka. Mashruucan waxa uu ku talinayaa in la bedelo Buundada Wadada Cedar Lake. Buundada la bedelayo waxaa ka mid ah agabka gaadiidka xamuulka qaada, dadka lugeynaya, iyo bushkuleetiyo iyada oo la raacayo nidaamka u degsan Sharciga Qorsheynta Gaadiidka iyo Tilmaamaha Naqshadda.

### Goobta Mashruuca



Project Location



### Ujeedooyinka Waaxda Hawlaha Guud

- o Horumarinta waddo lugeedyada iyo amaankooda
- o Horumarinta isku xirka bushkuleetiyo
- o Maritaanka Gaadiidka
- o Isku xirka mashariicda iyo qorshaha hay'adaha gacansaarka la leh

### Jadwalka Mashruuca Qorsheynta Naqshadda Dhismaha Ka Hor

Qorsheynta Naqshadda Dhismaha Ka Hor



### jadwalka mashruuca



### Xaaladda Iminka Jirta



### Qiyaasta Tirada dadka Isticmaala Maalin Kasta

460\*  
lugeeye

160\*  
Bushkuleetiyo

1,500  
Gaadiidka

\*Xog la soo ururiyey 2017 ee Koonfurta Wadada Cedar Lake Road, bariga Koonfurta Wadada Penn South (u jirta 0.2 meyl goota mashruuca)

### Shilalka La Soo Sheegay

Ma jirin wax shilal ah oo la soo sheegay oo ka dhacay goobta mashruuca tobankii sano ee la soo dhaafay.

Source: MnDOT 2021