



Barr Footer: ArcGIS 10.0, 2011-06-06 11:10:59, 100000 File: I:\Client\BassettCreek\Work_Orders\BassettCreek\FeastibilityStudy_2011\Map\BassettCreek\Fig02 Proposed Stabilization Practices.mxd User: kac2

- Stationing Centerline
 - 2012 Restoration Sites
- Erosion Sites**
- Bank Failure
 - Bank Scour
 - Hill Slope
 - Picture
 - Grading




Figure 2

PROPOSED STABILIZATION PRACTICES
2012 Bassett Creek Main Stem Restoration Project
Bassett Creek Watershed Management Commission