

Minneapolis HPC Building Inventory Form

P.I.D.

2119 West Broadway

Property and Owner Information

Historic Name Delisi Building
Common Name Commercial Building
Other Name _____
State Inventory # HE-MPC-07015

Owner Code P=Private; L=Local; S=State; F=Federal
Current Owner _____
Address _____
City _____ State _____ Zip _____

Locational Information

ZONE 15 Quad Minneapolis North, Minnesota
E 475750 TWP 29N RG 24W Sec. 16
N 4983160 Quarter/Quarters _____

Blk 21 Lot(s) 12, 13, 1 Addition Forest Heights
No. 2119 Street West Broadway
City Minneapolis County Hennepin
Zip _____ Neighborhood: _____

Survey/Photography Information

Surveyor(s) Nathan Weaver Olson and Charlene R
Survey Date 08/01/2001 Co. Hess Roise
Building Occupied? Publicly Accessible?
Survey Level 1. No Significance
Photographer Nathan Weaver Olson
Photo Date 08/01/2001 Roll _____
Frame 20 Facing _____
Frame _____ Facing _____
Frame _____ Facing _____
Frame _____ Facing _____

Contact Sheet B

Notes:

Significance and Nomination Information

Property Category Building Period of Significance _____ Level of Sig. L=Local; S=State; N=National
NRHP Status Not eligible Local Status Not eligible NHL Date _____
Date _____
Ref. No. _____ In District C = Contributing NC=Noncontributing
In District C = Contributing NC=Noncontributing
Significant Person _____ Cultural Affiliation _____
Local Criterion _____
Local Contexts _____
State Context _____
Note on Significance: _____ Threats: _____

Consultant No further work recommended.
Recommendation:

Minneapolis HPC Building Inventory Form

P.I.D. _____

2119 West Broadway

Building Information/Historical Background

Architect/Engineer _____
 Other Designer _____
 Builder/Contractor _____
 Landscape Architect _____
 Original Owner _____
 Biographical Info: _____

Construction Date 1914
 Current Function Business
 Original Function Unknown
 Other Functions _____
 Other Owners and Biographies: _____

Oral Histories: _____

Published Sources: _____

Bldg. Permit Info: _____

Sanborn/Atlas Info: _____

City Directory Info: _____

Other Sources: _____

Historical Photos: _____

Other Historical Info: _____

Architectural Information

Stories _____ Plan Shape _____ Height _____
 Style _____ Roof Shape _____ Acreage _____

Materials

Structure Brick
 Foundation _____
 Wall (Primary) Brick
 Wall (Secondary) _____
 Roofing _____
 Window Condition _____
 Type _____

Integrity

Material Condition _____
 Design Integrity _____
 Original Site?
 Alterations: _____

Notes on Architecture: Brick stores, hall and offices.

Notes on Interior: _____

Site Features

Outbuildings _____
 Site Features _____

Surrounding Land Use _____
 Integrity of Setting _____
 Importance of Setting _____

General Property Notes: _____

Reconnaissance-level Historical/Architectural Survey

West Broadway Avenue, Minneapolis, Hennepin County
Lyndale Avenue North to the western border of Minneapolis

Street Address: 2119 West Broadway

SHPO Inventory Number: HE-MPC-7015

Historic Name: Delisi Building
Current Name: commercial building

USGS Quad: Minneapolis North, Minnesota
UTM Coordinate: 15 475750 4983160
Township: 29 North
Range: 24 West
Section: 16

Legal Addition: Forest Heights
Block: 21
Lot: 12,13,14

Eligible for the National Register of Historic Places?

--As individual property: no
 --In historic district: no

Date Listed:
Criterion/Criteria:
Level of Significance:

Information from Minneapolis Building Permit
(available at the city of Minneapolis Inspections Office--the Public Service Center Building)

Date of Construction: 1914, 4/22
Construction Description: 67x88 brick stores, hall and offices

Surveyed by: Nathan Weaver Olson and Charlene Roise
Hess, Roise and Company, Minneapolis
Date: August 2001
Contact Sheet: B
Frame: 20

