

Minneapolis HPC Building Inventory Form

P.I.D. 0802824430001

4401 UPTON AVE S

Property and Owner Information

Historic Name Lake Harriet M.E. Church Owner Code P *P=Private; L=Local; S=State; F=Federal*
 Common Name Lake Harriet Spiritual Community Current Owner LAKE HARRIET SPIRITUAL COMM
 Other Name _____ Address 4401 UPTON AVE SO
 State Inventory # HE-MPC-06677 City MINNEAPOLIS State MN Zip 55410-

Locational Information

Blk _____ Lot(s) _____ Addition RGT FIRST DIV REM P
 ZONE 15 Quad MINNEAPOLIS SOUTH No. 4401 Street UPTON AVE S
 E 475164 TWP 28 RG 24 Sec. 8 City Minneapolis County Hennepin
 N 4974454 Quarter/Quarters SW SE Zip 55410 Neighborhood: Linden Hills

Survey/Photography Information

Surveyor(s) Mead & Hunt
 Survey Date 05/15/2005 Co. Mead & Hunt
 Building Occupied? Publicly Accessible?
 Survey Level Reconnaissance
 Photographer Mead & Hunt
 Photo Date 05/15/2005 Roll 4
 Frame 23 Facing NE
 Frame 24 Facing SE
 Frame _____ Facing _____
 Frame _____ Facing _____
 Contact Sheet 014900



Notes:

Significance and Nomination Information

Property Category Building Period of Significance 1916 Level of Sig. L *L=Local; S=State; N=National*
 NRHP Status _____ Local Status _____ NHL Date _____
 Date _____ Date _____
 Ref. No. _____ District Status _____
 In District *C = Contributing NC=Noncontributing; Name of District*
 Significant Person _____ Cultural Affiliation _____
 Local Criterion 4. Architecture/Engineering/Construction
 Local Contexts Architecture Religion and Social Organization _____
 State Context Urban Centers 1870-1940
 Note on Significance: C: Architecture Threats: _____

Consultant Recommendation: Recommended individually eligible for local and/or National Register designation based on preliminary research.

Building Information/Historical Background

Architect/Engineer Fulton and Bulter
Other Designer _____
Builder/Contractor Sonner, P.J.
Landscape Architect _____
Original Owner Lake Harriet M.E. Church
Biographical Info: _____

Construction Date 1916
Current Function Religion
Original Function Religion
Other Functions _____
Other Owners and Biographies: _____
Oral Histories: _____

Bldg. Permit Info: Permit on file at the City of Minneapolis Inspection office.

Published Sources: Property identified in the Down at the Lake (Linden Hills History Study Group, 2001).

Sanborn/Atlas Info: _____

City Directory Info: _____

Other Sources: Property included in SHPO inventory files.

Historical Photos: _____

Historical Info: _____

Architectural Information

Stories 2 Plan Shape Rectangular Height _____
Style Neoclassical/Classical Revival Roof Shape Dome Acreage _____

Materials

Structure Brick
Foundation Brick
Wall (Primary) Brick
Wall (Secondary) _____
Roofing Asphalt Shingles
Window Condition Original windows/openings intact
Type fixed, multipane

Integrity

Material Condition Good
Design Integrity Good
Original Site?
Alterations: _____

Notes on Metal-plated dome, classical revival elements with a prominent pedimented entrance with ionic columns, cornice returns, stone Architecture: sills and watertable, multipane painted glass fixed windows above entrance doors, brick pilasters with stone capitals.

Notes on Interior: _____

Site Features

Surrounding Land Use Commercial
Integrity of Setting Good
Importance of Setting Somewhat Important

Outbuildings _____
Site Features _____
General Property CHURCH
Notes: _____